

WO #: PE14476

WO Desc: Head End of Chiller is Leaking Around Gasket/Flange Area (East End)

Parent WO#:

WO Long Desc:

WO Priority: 2

Location: I-HX-1200

RECIRCULATION CHILLER 2 HEAT EXCHANGER

Asset: 1347485

RECIRCULATION CHILLER 2 HEAT EXCHANGER

Asset Service:

Entry Date: 9/11/2009

WO Status: CLOSE

Action Code: CORR

Project #:

Originator: Douglas Thurman

Status Date: 3/30/2010

Work Type: CM

Failure Class: UNCLSS

Job Plan:

Planned Start:

Actual Start: 9/15/2009

Review Date:

PM/Bundle:

Planned Completion:

Actual Completion: 9/22/2009

Plant Information

RC: PERC01

Planner: WILLIAM STONEKING

MOC#:

When Code: RT

Lead Craft: MECH

MOC Status:

P&ID:

MOC Desc:

SIR/EIS Required:

Work Actuals Materials

Task ID	Stock No.	Noun Qualifier	PO	PO Line Num	Quantity
	016520	Bung, Pressure Relief, 2", Metal, P/N 2BG-13620			1
	900044	Gloves, Cobra, Fluoroelastomer/Nitril, Size 10,			2

Services Actuals

Line Type	Voucher	Service	Description	Line Cost
SERVICE	PEV23276		Labor and materials to remove and replace refrigerant	\$2,224.60

Completed by Emp #: _____

Signature: _____